Product Change Notification

Overview: Please be advised that the following is notice of change to Fire Research products for Navistar engine.

Products Affected: All engine throttle and governor product lines that support the Navistar engines.

Change Description: We are adding new kit part numbers to support the 2007 Navistar MaxxForce DT, 9, and 10 engines. Existing kit part numbers for Navistar engines with RESCM are not changing but these will not work with the MaxxForce engine ECM.

Reason For Change: The MaxxForce engines use a new ECM that requires different control signals from remote engine throttles and engine governors.

Replacement Product: FRC will continue to provide all kits to support Navistar engines with a RESCM installed. The new kit part numbers for MaxxForce can be identified by a –D in the type code (last three characters) of the kit part number as follows:

ELA104-D00	THROTTLEXCEL
ETA404-D00	INFINITY-PRO
ETA404-D01	INFINITY-PRO EP
PBA104-D00	PRES GOV PUMP-BOSS NAV-MAXX PSI F
PBA104-D02	PRES GOV PUMP-BOSS NAV-MAXX KPA C
PRA204-D00	PRES GOV PRO-S4D NAV-MAXX PSI
PRA204-D01	PRES GOV PRO-S4D NAV-MAXX KPA
TGA104-D00	INCONTROL1 NAV-MAXX PSI
TGA104-D01	INCONTROL1 NAV-MAXX KPA
TGA204-D00	INCONTROL2 NAV-MAXX PSI
TGA204-D01	INCONTROL2 NAV-MAXX KPA
TGA304-D00	INCONTROL3 NAV-MAXX PSI
TGA304-D10	INCONTROL3 NAV-MAXX KPA
TGA404-D00	INCONTROL4 NAV-MAXX PSI
TGA404-D10	INCONTROL4 NAV-MAXX KPA
FRA104-D00	GEN GOV FROG

References: No references are applicable.

Response: No response to this notification is required. Requests for additional information should be directed to an FRC sales representative at 1.800.645.0074.

FS 10SEP07