

Product Change Notification

Overview: Please be advised that the following is notice of change to the Fire Research RTU-11 Dial-Type Remote Throttle product line.

Products Affected: All RTU-11 Remote Hand Throttle models.

This includes the following current FRC part numbers:

RTA111-A00, RTA111-B00

RTA112-A00

RTA113-A00, RTA113-B00

RTA114-A00

RTA115-A00

RTA116-A00, RTA116-B00

RTA117-A00

RTA118-A00

(And all pre-2005 part numbers: RTU 11, RTU 11-iS. -2, -3, -4, -5, -6, -8)

Change Description: The above models are being discontinued immediately.

Reason For Change: The RTU 11 series, first released in 1994, has been rendered largely redundant by remote hand throttles using newer technologies. Engine ECMs using these newer technologies are not compatible with the older RTU 11 series.

Replacement Product: FRC will continue to provide service and parts for the RTU 11 throttles.

For replacements or new installations the Infinity (ETA series) remote engine throttle is recommended.

For new installations the ThrottleXcel (ELA series) integrates a remote engine throttle, display, and engine monitoring system in one compact module.

References: No references are applicable.

Response: No response to this notification is required. Requests for additional information should be directed to an FRC sales representative at 1.800.645.0074.