

Product Change Notification

Overview: Please be advised that the following is notice of change to the Fire Research InControl Governor TGA200 series.

Products Affected: All TGA200 governors with Metric displays (kPa or Bar) and some (dependent on engine/ECM type) TGA200 governors with English displays (PSI) which have a manufacturing date of on or about June 2005 through March 2007 and use the J1587 databus for transmission temperature input.

Governors using a separate transmission temperature sensor are not affected.

Change Description: The above models require a software update.

Reason For Change: There is a discrepancy in the software program that reads transmission temperature off the J1587 databus. It will cause all 10 segments of the transmission temperature display to illuminate (indicating maximum temperature) when the transmission temperature is below 140° F (60 °C).

Once the transmission comes up to normal operating temperature above 140° F (60 °C), the display will show the correct temperature.

Replacement Procedure: New software needs to be installed in the governor. Contact FRC Sales or Service to make arrangements for updating the software.

References: No references are applicable.

Response: No response to this notification is required. Requests for additional information should be directed to an FRC sales representative at 1.800.645.0074.