

Product Change Notification

Overview: Please be advised that the following is notice of change to the Fire Research INControl Pressure Governor TGA100 and TGA200 series for J1587 interface.

Products Affected: All TGA100 and TGA200 series governors manufactured after November 2007 (starting with serial number 349248).

Change Description: The software for the above products is being updated as follows:
The program that automatically calibrates the pump intake and pump discharge displays to 0 psi on power-up is removed.
The new calibration program requires operator input in order to calibrate the pump intake and pump discharge displays to 0 psi.

Note: The Pump Pressure Sensors calibration program should be run for initial installations.

Reason For Change: Part of the ongoing process to improve FRC products. This change will provide greater flexibility by allowing the end user to determine when it is necessary to calibrate the pump intake and pump discharge pressure displays.

Replacement Product: No replacements or updates are required.

References: Product manual document number XE-TGA1PM-R0A, file name and revision TGA100 Rev1207 (and forward), section Calibration, paragraph Pump Pressure Sensors.

Response: No response to this notification is required. Requests for additional information should be directed to an FRC sales representative at 1.800.645.0074.